


Standard Process



~For soft concrete add an additional densification step before the 00's~
~If transitioning from metals, switch to 00 after to 50 grit~